

ECTOR COUNTY: US 385

SH 158 Interchange to 2,000 ft. North of Interchange



Existing Conditions

» High speeds by vehicles on US HWY 385

» Most crashes are occurring at the interchanges

Crash Summary

27	Total Crashes	0	Pedestrian Crashes
2	Fatal Crashes	0	Bicyclist Crashes
1	Suspected Serious Injury Crashes	20	Intersection Related Crashes
9	Suspected Minor Injury Crashes		



Safety Emphasis Areas

Roadway & Lane Departures

Distracted Driving

Impaired Driving

Intersection Safety

Occupant Protection

Speed Related

Vulnerable Road Users

Ector County: US HWY 385

This corridor is classified as an “Other Principal Arterial” and has a speed limit of 75 MPH. Most of the corridor is a 4-lane divided roadway with two travel lanes in each direction but widens near the interchange to include dedicated right turn lanes and acceleration lanes. Located on the other side of the interchange there are a couple of industrial businesses.

