

# UPTON COUNTY: SH 349

From 1,000 ft. South of CR 115 to 2,500 ft. North of CR 205


## Existing Conditions

- » Narrow paved shoulders
- » Horizontal curve in the middle of the corridor
- » Speeds too high for the curve


## Crash Summary

|    |                                  |   |                              |
|----|----------------------------------|---|------------------------------|
| 26 | Total Crashes                    | 0 | Pedestrian Crashes           |
| 3  | Fatal Crashes                    | 0 | Bicyclist Crashes            |
| 1  | Suspected Serious Injury Crashes | 1 | Intersection Related Crashes |
| 3  | Suspected Minor Injury Crashes   |   |                              |

## Contributing Factors



## Manners of Collision



## Safety Emphasis Areas

Roadway & Lane Departures

Distracted Driving

Impaired Driving

Intersection Safety

Occupant Protection

Speed Related

Vulnerable Road Users

## Upton County: SH 349

This section of SH 349 is a 3-lane undivided roadway with a speed limit of 75 MPH. While the surrounding areas are oil fields, the Upton Landfill is located near the center of the corridor. Due to the landfill and oil fields, this corridor experiences a large volume of heavy truck traffic.

## Corridor Recommendations

Widen Paved Shoulders

Lighting

Appropriate Speed

