

BORDEN COUNTY: US 180

Private Drive to 6,200 ft. from Private Drive


Existing Conditions

- » Vertical Crest hinders sight distance
- » Private drives of businesses lack lighting


Crash Summary

6	Total Crashes	0	Pedestrian Crashes
1	Fatal Crashes	0	Bicyclist Crashes
1	Suspected Serious Injury Crashes	0	Intersection Related Crashes
1	Suspected Minor Injury Crashes		

Contributing Factors



Manners of Collision



Safety Emphasis Areas



Roadway & Lane Departures



Distracted Driving



Impaired Driving



Intersection Safety



Occupant Protection



Speed Related



Vulnerable Road Users

Borden County: US HWY 180

This section of US HWY 180 is a rural corridor. The study corridor is a 2-lane undivided roadway and is classified as an “Other Principal Arterial”. The posted speed limit is 75 MPH. There are no intersections along this corridor except for a private drive located at the western most end of the corridor.

Corridor Recommendations



Rumble Strips



Speed Limit Signs



Intersection Lighting



Centerline Widening



Speed Feedback Sign



Solid Yellow Centerline



“No Passing” Signage



“Deer Crossing” Sign

