

FM 1788 & SH 349

Midland County


Existing Conditions

- » Heavy freight traffic present due to the businesses located along the intersection
- » Intersection safety issues based on the percentage of T-bone crashes occurring


Crash Summary

73	Total Crashes	0	Pedestrian Crashes
4	Fatal Crashes	0	Bicyclist Crashes
6	Suspected Serious Injury Crashes	64	Intersection Related Crashes
17	Suspected Minor Injury Crashes		

Contributing Factors



Manners of Collision



Safety Emphasis Areas



Roadway & Lane Departures



Distracted Driving



Impaired Driving



Intersection Safety



Occupant Protection



Speed Related



Vulnerable Road Users

Midland County: FM 1788 & SH 349

This intersection is between a 2-lane undivided road (SH 349) and a 3-lane undivided road (FM1788). SH 349 being classified as a minor arterial and FM 181 as a major collector. Speed limit along around the intersection are 65 MPH. Due to industrial and residential areas near the study location, there are several minor road approaches onto the main roads of focus that show a need for safety improvements.

