

ECTOR COUNTY: N. COUNTY RD. W.

W. 16th St. to W. 24th St.


Existing Conditions

- » High density of driveways near major intersections
- » Two bus stops located on the corridor
- » San Jacinto Park towards the end of corridor


Crash Summary

251	Total Crashes	2	Pedestrian Crashes
2	Fatal Crashes	1	Bicyclist Crashes
5	Suspected Serious Injury Crashes	113	Intersection Related Crashes
29	Suspected Minor Injury Crashes		

Contributing Factors



Manners of Collision



Safety Emphasis Areas



Roadway & Lane Departures



Distracted Driving



Impaired Driving



Intersection Safety



Occupant Protection



Speed Related



Vulnerable Road Users

