

FM 181 & KERMIT HWY INTERSECTION

Andrews County


Existing Conditions

» Ongoing construction of an overpass


Crash Summary

74	Total Crashes	0	Pedestrian Crashes
4	Fatal Crashes	0	Bicyclist Crashes
9	Suspected Serious Injury Crashes	74	Intersection Related Crashes
15	Suspected Minor Injury Crashes		

Contributing Factors



Manners of Collision



Safety Emphasis Areas



Roadway & Lane Departures



Distracted Driving



Impaired Driving



Intersection Safety



Occupant Protection



Speed Related



Vulnerable Road Users

Andrews County: FM 181 & SH 115

The intersection between FM 181 and SH 115 consisted of two 2-lane, undivided roadways with speed limits of 75 MPH. During the study period the intersection has become grade separated. The grade will alter the current cross sections of the intersection roadways. The surrounding area is extremely rural with little no residences or businesses. Although there are little residences or businesses, there is increased volumes of heave freight traffic passing through due to the connection SH 115 provides.

